

# Jay Bangs – Unnamed Ephemeral Drainage

## Aerial Overview – Before and After BDA Installation



**Observations:** Imagery collected in late May 2026 (approximately 8 months after BDA installation) shows surface water retained at all three BDA locations while much of the surrounding drainage remains dry. These observations indicate that the BDAs are functioning as intended to increase water storage and extend the hydroperiod.